PROJECT: SRMS ASS'Y MONEHICLATURE: END EFFECTOR

SYSTEM: MECHANICAL ARM SUBSYSTEM ASS'Y P/N: 51140E1470-3

SHEET: _____

FHEA REF.	MEV. OR	ME OTY 4 TANÍNG RÉF. SIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HOWR / FUNC. 2/IRAB RATIONALE FOR ACCEPTANCE CRITICALITY
3731	SN HE	PTURE/ IARE CHAMISM Y-I RT OF 140E 1477-3	HODE: PRINE CAPTURE/ SMARE BRAKE SLIP. CAUSE(S): (1) STRUCTURAL FAILURE. (2) MELHANICAL FAILURE (SUIDE PIN ETC). (3) FRICTION DEBRIS INCRESS WITH EXCESSIVE BRAKE PAD WEAR.	MONE. RIGIDIZATION BRAKE HOLDS SYSTEM. WORST CASE LOSS OF MISSION. SUBSEQUENT FAILURE MAY CAUSE UNCUMMANULU RELEASE. REDUNDANT PATHS REMAINING RIGIDIZE BRAKE.	THE EMD EFFECTOR BRAKE IS A MAJOR BOUGHT-OUT-PART WHICH IS SUPPLIED BY SPERRY CORPORATION, AEROSPACE AND MARINE GROUP AND MEETS OR EXCEEDS THE REQUIRENTISTS OF SPECIFICATION STAR-SC. 1091. THE END EFFECTOR CALIPER BRAKE IS A MAJOR BOUGHT-OUT-PART WHICH IS SUPPLIED BY SPERRY CORPORATION, AEROSPACE AND MARINE GROUP AND MEETS OR EXCEEDS THE REQUIRENTISTS OF SPECIFICATION SPAR-SC. 451, 15SUE E P/M SILADOZZI9-I FOR BOTH THE SMARE AND MALINIZE BRAKE INCORPORATES MANY DESIGN FEATURES TO IMPROVE THE BRAKES CAPABILITY AND GIVE HIGHER RELIABILITY AS FOLLOWS: - SLIP TORQUE CAPABILITY UP TO 85 QZ-IM TOTAL INTERNAL CONTAINMENT OF FRECTION DEBRIS MITH THE USE OF LABYRINTH PATHS AND THE PLACEMENT OF THE FRICTION DISKS ON THE OPPOSITE END OF THE BRAKE SHATT FROM THE PINION CEAR MECHANICALLY REDUNDANT SLIDING SPLINES FOR THE CALIPER DISK MECHANICALLY REDUNDANT LOCATING PINS MITH VESPEL SLEEVES FOR DISK LOCATION BEARING LOADS ARE REDUCED BY A 5 TO 1 FACTOR OVER THE ORIGINAL CYC. SMARE BRAKE P/M SILADOS74-3 SLIDING SURFACES ARE LUBBRICATED WITH MOLYBORNUM DISULFIDE BEARINGS ARE MEY LUBRICATED WITH MOLYBORNUM DISULFIDE BEARINGS ARE MEY LUBRICATED WITH MOLYBORNUM DISULFIDE AIR GAP CAM BE ADJUSTED WITHOUT BRAKE DISASSEMBLY. DESIGN STANDARDS REQUIRE AN HULTIHATE FACTOR OF SAFETY OF 1.4 FOR SHARE MEY LUBRICATED WITH BRANCE IL-3BRP AIR GAP CAM BE ADJUSTED WITHOUT BRAKE DISASSEMBLY. DESIGN STANDARDS REQUIRE AN HULTIHATE FACTOR OF SAFETY OF 1.4 FOR SHARE MEY LUBRICATED WITH BRAKE COSSIGN WHICH PROCLARE TOOR OF SAFETY OF 1.4 FOR SHARE MEY LUBRICATED WITH BRAKE OLSASSEMBLY. THE BRAKE USES FOUR PINS PRESS FITTED INTO THE CORE TO HOLD THE ARRATURE FROM ROTATING AND TO ALLOW ANIAL SLIBING FOR EMAGEMENT. THE FOLLOWING IS A LIST OF CHARACTERISTICS TO LITHIT THE POSSIBILITY OF THE BRAKE CORE PINS TO ASSURE ADDOUGH WITH THE WINT THE STEED AND THE THOM THE CORE TO ASSURE ADEQUATE CLEARANCE. THE HOLES IN THE ARRATURE AND BRAKE CORE ARE NATCH-BORD THE FOUR APPLICATION OF VOLTAGE WITH FILE THE TWO ASSEMBLED PARTS. TH

PREPARED BY: WW.

PROJECT: SRMS ASS'Y MOMENCLATURE: END EFFECTOR

SYSTEM: NECHANICAL ARM SUBSYSTEM ASS'Y P/N: STITUTE 170-3

THEA REF.	REV.	HAHE OTY L DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	ROUR / FUNC. 2/IRAB RATIONALE FOR ACCEPTANCE CRITICALITY
3731	0	CAPTURE/ SNARE HECHANISH QTY-I PART OF S114DE 1477-3	MODE: PRIME CAPTURE/ SMARE BRAKE SLIP. CAUSE(S): (1) STRUCTURAL FAILURE. (2) MECHANICAL FAILURE (GUIDE PIN ETC). (3) FRICTION DEBRIS IMGRESS WITH EXCESSIVE BRAKE PAD WEAR.	NOME, RIGIDIZATION BRAKE HOLDS SYSTEM. WORSE CASE LOSS OF MISSION. SUBSEQUENT FARLURE MAY CAUSE UNLUMNAMBLU RELEASE. REDUMDANT PATHS REMAINING RIGIDIZE BRAKE.	THE PINS ARE LUBRICATED WITH MOLYODENUM DISULFIDE. THE HEAVIEST AMOUNT OF FRICTION MATERIAL DEBRIS IS GENERATED DURING THE CALIBRATION BUW-IN OF THE UNIT. THE RUM-IN CONSISTS OF ROTATING THE UNIT IN ONE DIRECTION AT 50 RPM FOR A TOTAL OF 16 HOURS MINHHUM ISING A DUTY CYCLE OF 10 SECONDS ENCAGED AND THEN 10 SECONDS DISTMOACED. THE UNITS RECEIVE A VERY LIMITED AMOUNT OF SLIPPING DURING ON MISSION WISAGE. THE STATE OF THE UNIT IS VERIFIED TO MEET A MINIMUM VALUE BY THE ANY CAPTURED FOR THE LIMIT STATE OF THE LIMIT SETTING. THE STATEDOUM AND INSPECTION OF FLIGHT MARDMARE RETURNED FOR REFURBISHMENT HAS REVEALED THAT A SIGNIFICANT AMOUNT OF FRICTION MATERIAL DEBRIS MAY HAVE ACCUMULATED AT THE UNIT END-OF-LIFE. IT IS VERY WINLIKE IF, HOUR VER THAT SUFFICIENT FRICTION DEBRIS CONLD ACCUMULATE BEHIND THE ARRATURE OR PRINCIPLE CONTROL DEBRIS CONLD ACCUMULATE BEHIND THE ARRATURE OR PRINCIPLE THE FRICTION SURFALES. SO AS TO AFFECT THE UNITS PRINCIPLE HIM FRICTION SURFALES. SO AS TO AFFECT THE UNITS
4000000			UPERCEDING DATE:	06 OCT 87 APP	ROVED BY:

PROJECT: SAMS ASS'Y MOMENCEATURE: END EFFECTOR SYSTEM: MECHANICAL ARM SUBSYSTEM
ASS'Y P/M: STI40ET470-1 SHEET:

MEA NAME OTY & FAILURE MODE FAILURE EFFE LF. REV. DRAWING REF. AND ON DESIGNATION CAUSE END LICH	T HOUR / FUNC. 2/IRAB RATIONALE FOR ACCEPTANCE CRIFFCALITY
O CAPTURE/ SMARE MECHANISH OTY-1 PART OF S1140E1477-3 REGRANISH ECHANISH OTY-1 PART OF S1140E1477-3 REGRANE SLIP. CAUSE(S): (1) STRUCTURAL FAILURE. (2) MECHANILAL FAILURE (GUIDE PIN ETC). (3) FRICTION DEBRIS INCRESS WITH EXCESSIVE BRAKE PAD WEAR. REDUNDANT PAI REHALINING RIGIDIZE BRAK RIGIDI	THE EE ASSEMBLY QUALIFICATION TESTING CONSISTED OF THE FOLLOWING ENVIRONMENTS:

PROJECT: SRMS ASS'Y MOMENCEATURE: END EFFECTOR

SYSTEM: HECHANICAL ARM SUBSYSTEM

ASS'Y P/H: STTADETAYO-3 SHEET: 4 MAHE OTY E TAILURE HODE TAILURE EFFECT HOWR / FUNC. MEF. REV. DRAWING ACF. Z/IRAB DESIGNATION CAUSE RATIONALE FOR ACCEPTANCE END LICH CRITICALITY 3731 0 CAPTURE/ MONE **OA/INSPECTIONS** SHARE PRIME RIGIDIZATION MECHANISH CAPTURE/ BRAKE HOLDS Q1Y-1 SWARE SYSTEM UNITS ARE MANUFACTURED UNDER DOCUMENTED QUALITY CONTROLS. PART OF BRAKE SLIP. THESE CONTROLS ARE EXERCISED THROUGHOUT DESIGN 51140E1477-3 WORST CASE PROCURENENT, PLANNING, RECEIVING PROCESSING, FABRICATION, ASSEMBLY, FESTING AND SHIPPING OF THE UNITS, MANDATORY CAUSE(S): LOSS OF INSPECTION POINTS ARE EMPLOYED AT VARIOUS STAGES OF STÁUCTURAL MISSION. FABRICATION ASSEMBLY AND TEST. COVERNMENT SOURCE FAILURE. SUBSEQUENT INSPECTION IS INVOKED AT VARIOUS CONTROL LEVELS. FAILURE MAY CAUSE RECEIVING INSPECTION VERIFIES THAT THE HARDWARE RECEIVED IS AS MECHANICAL **UNCOMMANDED** IDENTIFIED IN THE PROLUBEMENT DOCUMENTS, THAT NO DAMAGE HAS FAILURE RELEASE. OCCURRED DURING SHIPMENT, AND THAT APPROPRIATE DATA HAS BEEN (GUIDE PIN RECEIVED WHICH PROVIDES ADEQUATE TRACEABILITY INFORMATION AND ÉTC). REDUNDANT PATHS IDENTIFIES ACCEPTABLE PARTS. REMAINING (3) FRICTION PARTS ARE INSPECTED THROUGHOUT MANUFACTURE AND ASSEMBLY AS ÖEÁRIS RIGIDIZE BRAKE. APPROPRIATE TO THE MANUFACTURING STAGE COMPLETED. THESE INCRESS WITH INSPECTIONS INCLUDE. EXCESSIVE BRAKE PAD FOLLOWING HEAT TREATMENT, STEEL PARTS (E.G. GEARS) ARE SUBJECTED TO A RAGRETIC PARTICLE INSPECTION FOR CRACKS OR IN WEAR. THE CASE OF ALUMINUM PARTS (E.G. HOUSINGS) ARE DYE PENETRANT EMSPECTED USING GROUP V PENETRANTS. HELDING OF GEARS OR HOUSINGS IS SUBJECTED TO DYE PENETRANT (GROUP V) AND RADIOGRAPHIC INSPECTION ON COMPLETION OF STRESS RELIEF TO CHECK FOR CRACKS. QUALIFICATION WELDING TEST SAMPLES FOR STRUCTURAL HELDS ARE SUBJECTED TO DESTRUCTIVE TESTING WHERE POSSIBLE (TENSILE AND BENDING) AS HELL AS METALLAGRAPHIC AMALYSIS TO ENSURE DEFECT FREE WELDS. FRACTURE CRITICAL COMPONENTS ARE INSPECTED TO THE APPLICABLE PROCESS CONTROL PROCEDURE USING SPECIAL NOT METHODS BY TRAINED AND CERTIFIED INSPECTORS. BEARINGS RECEIVE DIMENSIONAL INSPECTION AT THE SUPPLIER AND VERIFICATION BY SPAR RECEIVING INSPECTION. PRE-ASSEMBLY INSPECTION VERIFIES CIRCULARITY OF BALL TRACKS AND IMMER/OUTER RACE DIAMETERS, AFTER ASSEMBLY PRIOR TO LUBRICATION, RADIAL CLEARANCE MEASUREMENTS ARE TAKEN. FOLLOWING LUBAICATION, RUN-IN/BURNISHING AND CLEANING OF DAY LUBE BEARINGS, SPECIALIZED BEARING INSPECTION EQUIPMENT AT SPAR IS USED TO VERIFY QUALITY AND STICTION LEVELS THROUGH STRIP CHART RECORDING OF TORQUE TRACES, DEARINGS ARE THEN RETURNED TO THE SUPPLIER FOR FINAL RADIAL CLEARANCE HEASURENEHTS. GOVERNMENT SOURCE INSPECTION IS ENVOKED ON ALL BEARING PROCURERENTS. INSPECTION VERIFIES THAT KITTED PARTS ARE CORRECT PRIOR TO ASSEMBLY AND TRACEABILITY INFORMATION RECORDED. INSPECTION TO DRAWING IS CONDUCTED THROUGHOUT THE ASSEMBLY PROCESS, INCLUDING INSPECTION OF LOCKING WITHESSING OF TOROUTHE AND APPLICATION OF TOROUT STRIPING. PRE-ACCEPTANCE TEST INSPECTION, WHICH INCLUDES AN AUDIT OF

	—-l — —- — — l . , <u>. , . , </u>	VERIFIC	CATION TO AS DESIGN ETC. (MANDATORY INS	FIGURATION
MERIACO OV: WING	SUPERCEDING DATE: 04 OCT 87	APPROVED BY:	DATE THE THE THE THE THE THE THE THE THE T	PECTION POINT).

PROJECT: SRMS
ASS'V MONENCERTURE: CND CIVECTOR
SYSTEM: MECHANICAL ARM SUBSYSTEM
ASS'V P/N: STIROCIETUS
SHEET: 5

PHEA REF.	ACV.	PRAVING ACT.	PATEURE ROSE AND CAUSE	PATEUME ETTECT ON END LIEN	HOWN / FUNC. 2/IRAB RATIONALE FOR ACCEPTANCE ERITICALITY
2731		CAPTURE/ SPARE MECHANISM QTT-1 PART OF S1100E1477-9	MODE: PRIME CAPTURE/ SMARE BRAME SLIP. CAUSE(S): (1) SIRUCTURAL FAILURE. (2) RECMANICAL FAILURE (GUIDE PIR ETC). (3) FRICTION DEDRIS INCRESS WITH EXCESSIVE BRAKE PAR	MOME. RIGIDIZATION BRAKE HOLDS SYSTEM. MORST CASE LOSS OF RISSION. SUBSEQUENT FAILURE HAT CAUSE UNLORMANDED RELEASE. REDUMDANT PATHS REMAINING RIGIDIZE BRAKE.	A TEST READINESS REVIEW (FRR) WHICH INCLUDES VERIFICATION OF TEST PERSONNEL, TEST DOCUMENTS. TEST EQUIPMENT CALIBRATION / VALIDATION SINUS AND MARDMARK CONTIQUATION AS CONVENTO BY QUALIFIT ASSUMANCE IN COMJUNCTION WITH EMCINETING AND THE GOVERNMENT REPRESENTATIVE PRIOR TO THE STAND OF ANY FORMAL TESTING (ACCEPTANCE OR QUALIFICATION). ACCEPTANCE TESTING (AFF) INCLUDES, AMBIENT VIBRATION AND THERMAL HAC SESTING (SPAR/GOVERNMENT REP. RAMOATORY INSPECTION POINT). SARS SYSTEMS INTECRATION THE INTEGRATION OF MECHANICAL ARM SUBASSEMBLIES AND INCLUDES CONTINUED TO FORM INCLUDES AND THE STANDARD OF MECHANICAL ARM SUBASSEMBLIES AND INCLUDES CONTINUED. THIS PROCEDURE ROUTING, INCLUDES CONTINUED OF METHOD OF METHOD HACK SHAW MARPING CONCESS WILLIAM ROUTING, INTEGRACE AND MARPING CONCESS WILLIAM ROUTING, INTEGRAL ACCOUNTACTS ETC. SARPS SYSTEMS RESTING SERVING OF PUSH BACK CONTACTS ETC. SARPS SYSTEMS RESTING SERVING OF PUSH BACK CONTACTS ETC. SARPS SYSTEMS RESTING SERVING OF PUSH BACK CONTACTS ETC.
EPANED BY:			CERTIFIC BATT OF C		

APPROVED BY: _

RMS/MECH - 93 ---

PROJECT: SRMS
ASS'Y NOVENCLATURE: END EFFECTOR

SYSTEM: MECHANICAL ARM SUBSYSTEM
ASS'Y P/N: 51140E1470-3 SHEET: 6

REF.	REV.	DRAWING REF. DESIGNATION	FAYLUNE MODE AND CAUSE	FATLUME EFFECT OM END LIEM	HOUR / FURC. 2/18AB RATIONALE FOR ACCEPTANCE CRITICALITY
3731		CAPTURE/ SMARE MECHANISM GTY-1 PART OF 51140E1477-3	MODE: PRIME PRIME/ SMARE BRAKE SLIP. CAUSE(8): (1) STRUCTURAL FAILURE. (2) MECHANICAL FAILURE (GUIDE PIN ETC). (3) FRICTION DEBRIS INGRESS WITH EXCESSIVE BRAKE PAO MEAR.	NOME, RIGIDIZATION BRAKE HOLDS SYSTEM. WORST CASE LOSS OF HISSION. SUBSION. SUBSION. SUBSION. FAILURE HAY CAUSE UNCOMMANDED RELEASE. REDUNDANT PATHS REMAINING. RIGIDIZE BRAKE.	THE FOLLOWING FAILURE ANALYSIS REPORT(S) ARE RELEVANT: FAR 2404: 5 UNITS (S/NS 301, 302, 303, 304, 305) E/E GRAKE AUG. 87 DESCRIPTION ALL UNITS TAILED DROP-OUT & RELEASE TIME DUE TO A DESIGN ERROR CORRECTIVE ACTION MODIFIED DIAG. TO ASSURE CORRECT GAP LENGTH. MODIFIED CALIBRATION PROCEDURE (WHICH SERVES AS A M.1.P.).
L.—			·		AVE

PREPARED BY: MFWG

SUPERCEDING DATE: 12 OCT 89

APPROVED BY:

ATE: ___

REV.

0

REF.

1731

POSPARED BY, MEMO

MANE OTY & DRAWING REF.

DESIGNATION

CAPTURE/

MECHANISM

S1140E1477-3

SMARE

QTY-I

PART OF

TAILUNE HODE

AND

CAUSE

BRAKE SLIP.

CAUSE(5):

STAUCTURAL

HECHANILAL

(GUIDE PIN

(3) FRICTION DEBRIS

INCRESS WITH EXCESSIVE

BRAKE PAD

HEAR.

FAILURE.

FAILURE

ÉTC).

1300M

PRIME

SMARE

CAPTURE/

PROJECT: SAMS ASS'Y NOMENCLATURE: END EFFECTOR

HOUA / FUNC.

2/IRAB

CRITICALITY

OPERATIONAL EFFECTS

CREM ACTION

MISSION CONSTRAINT

TAILURE EFFECT

ON

END ITCH

RIGIDIZATION

BRAKE HOLDS

HORST CASE

SUBSEQUENT

FAILURE MAY CAUSE

UHLUMMANDED

REDUNDANT PATHS REMAINING

RIGIDIZE BRAKE.

RELEASE.

SYSTEM.

LOSS OF

MISSION

SYSTEM: MECHANICAL ARM SUBSYSTEM ASS'Y P/H: 51140E1470-3 SHEET: RATIONALE FOR ACCEPTANCE NONE. FOR SUBSEQUENT FAILURE. PAYLOAD HILL BE RELEASED WITH NO OPERATOR COMMAND, IF THIS OCCURS WHILE THE ARM IS BEING DRIVEN, THE PAYLOAD WILL TAKE AN UNEXPECTED TRAJECTORY. MANEUVER AND AND UNBITER AWAY FROM PAILOAD. THE EE RODE SWITCH SHOULD ONLY BE OUT OF THE OFF POSITION WHEN THE EE IS IN THE CAPTURE ENVELOPE OF A BERTHED PAYLOAD OR IMMEDIATELY PAIOR TO A FREE FLYING CAPTURE. THE SWITCH SHOULD BE PLACED BACK IN THE OFF POSITION IMMEDIATELY AFTER THE SPEC CAPTURE AND RIGIDIZE (REL/DERIG) TIMES HAVE ELAPSED. THE CREW SHOULD BE TRAINED TO OPERATE UNDER VERNIER RATES WITHIN 10 FT OF STRUCTURE. THE OPERATOR HUST BE ABLE TO DETECT THAT THE ARM/PAYLOAD IS RESPONDING PROPERLY TO COMMANDS VIA WINDOW AND/OR CCTV VIEWS DURING ALL ARM OPERATIONS. THE CREW FRAIMING

	AND/OF CLIV VIEWS DURING ALL ARM OPERATIONS. THE CREW TRAINING MUST PREPARE THEM TO BE ABLE TO MANEUVEN THE ORBITER AWAY FROM A FREE PAYLOAD AT ANY TIME DURING ARM OPERATIONS.
	SCREEN FAILURES
	N/A
	OHRSD OFFLINE
	PERFORM MANUAL RIGIDIZATION. WITH GRAPPLE FIXTURE PRESENT VERIFY SMARE CABLES DO NOT OPEN DURING RIGIDIZATION.
	DHRSD ONLINE INSTALLATION
	ноне
	ORRSD OHLINE TURNAROUND
	PERFORM MANUAL RIGID-PATION. WITH GRAPPLE FIXTURE PRESENT VERIFY SMARE CABLES DO NOT OPEN DURING RIGIDIZATION.
	RMS/MECH - 95
CONCECTABLE SETT. AL ACT AT APPROVE	